

APPROVED DISPENSATIONS**INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 24/10/2017 – 14/11/2017****DETAILS OF DISPENSATION**

Date: Sunday, 5 November 2017
Aircraft: A320
Registration: VH-VQC
Operator: Jetstar Airways
Operation: Departure

Circumstances Leading to Request: Jetstar Airways flight JQ750 (Launceston to Sydney) was ready to push back when a generator fault occurred. A requested and was granted a dispensation to land no later than 11:30pm. There were 153 passengers and six crew members on board. The aircraft landed at 11:14pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that the circumstances met the three criteria required for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Monday, 6 November 2017
Aircraft: A380
Registration: A7-APG
Operator: Qatar Airways
Operation: Departure

Circumstances Leading to Request: Qatar Airways flight QR909 (Sydney to Doha) had pushed back however some passengers became disruptive and the captain returned to bay. Passengers and baggage were off loaded. A dispensation was requested and granted to depart no later than 11:25pm. There were 385 passengers and 29 crew members on board. The aircraft departed at 11:21pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that the circumstances met the three criteria required for issue of a curfew dispensation.

DISPENSATION REQUESTS REJECTED**INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 24/10/2017 – 14/11/2017****DETAILS OF DISPENSATION**

Date: Sunday, 29 October 2017
Aircraft: B737-800
Registration: VH-VXG
Operator: Qantas Airways
Operation: Arrival

Circumstances Leading to Request: Qantas Airways flight QF557 (Brisbane to Sydney) encountered a delay due to thunderstorms in Brisbane. A dispensation was requested, however the circumstances were not immediate in origin. There were 149 passengers and seven crew on board.

Approved: No

Reasons for not granting Dispensation: The application did not meet the criteria required for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Sunday, 29 October 2017
Aircraft: A320
Registration: VH-VQQ
Operator: Jetstar Airways
Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ750 (Launceston to Sydney) were delayed on the previous sector. A dispensation was requested, however the circumstances were not immediate in origin. There were 145 passengers and seven crew members on board.

Approved: No

Reasons for not granting Dispensation: The application did not meet the criteria required for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Sunday, 29 October 2017
Aircraft: A320
Registration: VH-VNK
Operator: Tigerair Australia
Operation: Arrival

Circumstances Leading to Request: Tigerair Australia flight TT387 (Brisbane to Sydney) encountered a delay due to predicted thunderstorms in Brisbane. A dispensation was requested, however the circumstances were not immediate in origin.

Approved: No

Reasons for not granting Dispensation: The application did not meet the criteria required for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Saturday, 11 November 2017
Aircraft: A320
Registration: VH-JQG
Operator: Jetstar Airways
Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ524 (Melbourne to Sydney) had encountered a delay earlier changing aircraft and refuelling. A dispensation was requested, however the circumstances were not immediate in origin.

Approved: No

Reasons for not granting Dispensation: The application did not meet the criteria required for issue of a curfew dispensation.

DISPENSATION REPORT – OTHER CURFEW AIRPORTS #11/17

DETAILS OF APPLICATIONS 24/10/2017 – 14/11/2017

GOLD COAST AIRPORT:

Approved application

Date	Carrier	Aircraft Type	Movement	Summary of events
06/11/2017	AirAsia X	A330-300	Departure	AirAsia X flight XAX207 (Gold Coast to Kuala Lumpur) was delayed in boarding due to thunderstorm activity causing the tarmac to be evacuated several times. A dispensation was requested and granted to depart no later than 11:45pm. There were 287 passengers and 11 crew members on board. The aircraft departed at 11:36pm.

ADELAIDE AIRPORT:

No applications

ESSENDON AIRPORT:

No applications