

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 07/08/2023 – 03/09/2023

SYDNEY AIRPORT

DETAILS OF DISPENSATION

Date: 14 August 2023

Aircraft: A320

Registration: VH-VQF

Operator: Jetstar

Operation: Arrival

Circumstances Leading to Request: Jetstar flight JQ789 (Sunshine Coast to Sydney) was delayed arriving at Sydney Airport due to a security incident that impacted runway operations for over 4 hours at Sydney Airport. A dispensation was granted for landing no later than 23:30 local time. JQ789 had 143 passengers including 6 crew on-board. The aircraft arrived at 23:23 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 14 August 2023

Aircraft: A320

Registration: VH-VFF

Operator: Jetstar

Operation: Arrival

Circumstances Leading to Request: Jetstar flight JQ421 (Gold Coast to Sydney) was delayed arriving at Sydney Airport due to a security incident that impacted runway operations for over 4 hours at Sydney Airport. A dispensation was granted for landing no later than 23:59 local time. JQ421 had 168 passengers including 7 children, 1 infant, 1 wheelchair user and 6 crew on-board. The aircraft arrived at 23:31 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 14 August 2023

Aircraft: B787

Registration: VH-ZNG

Operator: Qantas

Operation: Departure

Circumstances Leading to Request: Qantas flight QF75 (Sydney to Vancouver) was delayed departing from Sydney Airport due to a security incident at Sydney Airport along with refuelling delays. A dispensation was granted for take-off no later than 23:50 local time. QF75 had 200 passengers and 14 crew on-board. The aircraft departed at 23:34 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 15 August 2023

Aircraft: A380

Registration: VH-OQG

Operator: Qantas

Operation: Departure

Circumstances Leading to Request: Qantas flight QF1 (Sydney to Singapore) was delayed departing at Sydney Airport due to an engineering issue that require an aircraft change. The new aircraft then required 4 fan blades changed on #4 engine and an engine run. The aircraft then had an Auxiliary Power Unit defect requiring start on bay and checks to be completed prior to pushback and taxi clearance. With all customers onboard and aircraft locked up ready to go, an intoxicated customer was then required to be offloaded.

A dispensation was granted for take-off no later than 23:30 local time. QF1 had 313 passengers including 2 unaccompanied minors and live animals and 14 crew on-board. The aircraft departed at 23:28 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 18 August 2023

Aircraft: B737

Registration: VH-VXK

Operator: Qantas

Operation: Arrival

Circumstances Leading to Request: Qantas flight QF498 (Melbourne to Sydney) was delayed arriving at Sydney Airport due to significant disruptions as a consequence of single runway operation at Sydney Airport. This disruption led to additional Air Traffic Control airborne holding up to and greater than 60 mins. A dispensation was granted for landing no later than 23:30 local time. QF498 had 174 passengers and 6 crew on-board and 2 pieces of must ride Medical Surgical related material. The aircraft arrived at 23:15 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 22 August 2023

Aircraft: B767

Registration: VH-XQU

Operator: Tasman Cargo Airlines

Operation: Departure

Circumstances Leading to Request: Tasman Cargo Airlines flight HJ002 (Sydney to Auckland) was delayed departing at Sydney Airport due to a weather event, with lightning causing ground crew to vacate the apron area. A dispensation was granted for take-off no later than 23:45 local time. HJ002 was a cargo flight with 2 crew on-board. The aircraft departed at 23:40 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 22 August 2023

Aircraft: A332

Registration: VH-EBK

Operator: Qantas

Operation: Arrival

Circumstances Leading to Request: Qantas flight QF652 (Perth to Sydney) was delayed arriving at Sydney Airport due to an unforeseen weather event and unscheduled runway change at Sydney. A dispensation was granted for landing no later than 23:15 local time. QF652 had 102 passengers and 10 crew on-board. The aircraft landed at 23:03 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 24 August 2023

Aircraft: A320

Registration: VH-VQE

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ532 (Melbourne to Sydney) was delayed arriving at Sydney Airport due to landing gear issues. A dispensation was granted for landing no later than 23:40 local time. JQ532 had 167 passengers including 3 children and 2 infants, and 6 crew on-board. The aircraft arrived at 23:31 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 26 August 2023

Aircraft: A350

Registration: B-LQG

Operator: Cathay Pacific

Operation: Departure

Circumstances Leading to Request: Cathay Pacific flight CX138 (Sydney to Hong Kong) was delayed departing Sydney Airport due to engineering issue that required an aircraft swap. A dispensation was granted for take-off no later than 23:30 local time. CX138 had 279 passengers including 3 wheelchair, 5 meet and assist, and 13 crew on-board. The aircraft departed at 23:18 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 26 August 2023

Aircraft: B787

Registration: VH-ZND

Operator: Qantas

Operation: Departure

Circumstances Leading to Request: Qantas flight QF73 (Sydney to San Francisco) was delayed departing from Sydney Airport due to engineering issues regarding the left-hand Auxiliary Power Unit generator, that required a full baggage removal, full de-board of passenger and full aircraft power down. A dispensation was granted for take-off no later than 23:45 local time. QF73 had 209 passengers and 13 crew on-board along with 2,649kg of live clams. The aircraft departed at 23:41 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 27 August 2023

Aircraft: A350

Registration: B-18902

Operator: China Airlines

Operation: Departure

Circumstances Leading to Request: China Airlines flight CI052 (Sydney to Taipei) was delayed departing from Sydney Airport due to engineering issues regarding the Auxiliary Power Unit fuel feed valve. A dispensation was granted for take-off no later than 23:59 local time. CI052 had 307 passengers and 15 crew on-board. The aircraft departed at 23:58 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 30 August 2023

Aircraft: A321

Registration: VH-VWX

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ987 (Perth to Sydney) was delayed arriving at Sydney Airport due to engineering issues regarding a waste tank sensor and a second fuel loading to counter Sydney weather. A dispensation was granted for landing no later than 23:20 local time. JQ987 had 216 passengers including 2 wheelchair and 7 crew on-board. The aircraft arrived at 23:05 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 30 August 2023

Aircraft: A320

Registration: VH-VGU

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ421 (Gold Coast to Sydney) was delayed arriving at Sydney Airport due to a boarding system outage that affected Jetstar flights across Australia. A dispensation was granted for landing no later than 23:45 local time. JQ421 had 186 passengers and 6 crew on-board. The aircraft arrived at 23:21 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 30 August 2023

Aircraft: A320

Registration: VH-VFV

Operator: Jetstar Airways

Operation: Departure

Circumstances Leading to Request: Jetstar Airways flight JQ611 (Sydney to Avalon) was delayed departing from Sydney Airport due to a boarding system outage that affected Jetstar flights across Australia. A dispensation was granted for take-off no later than 23:30 local time. JQ611 had 186 passengers and 6 crew on-board. The aircraft departed at 23:24 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 30 August 2023

Aircraft: A320

Registration: VH-VWU

Operator: Jetstar Airways

Operation: Departure

Circumstances Leading to Request: Jetstar Airways flight JQ527 (Sydney to Melbourne) was delayed departing from Sydney Airport due to a boarding system outage that affected Jetstar flights across Australia. A dispensation was granted for take-off no later than 23:30 local time. JQ527 had 230 passengers and 7 crew on-board. The aircraft departed at 23:29 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

REFUSED DISPENSATIONS

INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 07/08/2023 – 03/09/2023

There were no refused dispensations for Sydney Airport during this period.

APPROVED DISPENSATIONS**INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 07/08/2023 – 03/09/2023****ADELAIDE AIRPORT****DETAILS OF DISPENSATION**

Date: Monday 7 August 2023

Aircraft: A321

Registration: VH-OFW

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar flight JQ985 (Perth to Adelaide) was delayed departing from Perth Airport due to engineering issues with the forward cargo hold. A dispensation was granted for landing no later than 23:30 local time. JQ985 had 228 passengers including 2 wheelchair passengers and 7 crew. The aircraft landed at 23:08 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 9 August 2023

Aircraft: A320

Registration: VH-VGZ

Operator: Jetstar

Operation: Arrival

Circumstances Leading to Request: Jetstar flight JQ680 (Hobart to Adelaide) was delayed landing at Adelaide Airport due to a fuel imbalance identified at Hobart that required engineering attendance. Engineers were required to investigate the issue and re-balance the fuel in the tanks prior to departure. A dispensation was granted for landing no later than 23:30 local time. JQ680 had 185 passengers including 5 infants and 1 blind passenger and 6 crew on-board. The aircraft landed at 23:23 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 14 August 2023

Aircraft: B737

Registration: VH-YQG

Operator: Virgin

Operation: Arrival

Circumstances Leading to Request: Virgin flight VA442 (Sydney to Adelaide) was delayed arriving at Adelaide Airport due to a security incident that impacted runway operations for over 4 hours at Sydney Airport. A dispensation was granted for landing no later than 23:25 local time. VA442 had 147 passengers including 1 wheelchair user and 6 crew on-board. The aircraft arrived at 23:20 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 16 August 2023

Aircraft: A320

Registration: VH-VGJ

Operator: Jetstar

Operation: Arrival

Circumstances Leading to Request: Jetstar flight JQ680 (Hobart to Adelaide) was delayed arriving at Adelaide Airport due to engine fault. A dispensation was granted for landing no later than 23:45 local time. JQ680 had 160 passengers including 13 children, 2 infants, 2 wheelchair passengers, and 6 crew. The aircraft arrived at 23:24 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 16 August 2023

Aircraft: A321

Registration: VH-OFE

Operator: Jetstar

Operation: Arrival

Circumstances Leading to Request: Jetstar flight JQ985 (Perth to Adelaide) was delayed arriving at Adelaide Airport due to an engineering defect with no alternate aircraft available. Engineers completed repairs but were required to complete paperwork and conduct a repeat inspection prior to departure which caused further delay. A dispensation was granted for landing no later than 23:25 local time. JQ985 had 214 passengers including 15 children, 1 infant, and 7 crew on-board. The aircraft arrived at 23:15 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 25 August 2023

Aircraft: A320

Registration: VH-VFL

Operator: Jetstar

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ680 (Hobart to Adelaide) was delayed arriving at Adelaide Airport due to engineering checks in the previous sector which then require similar engineering checks before the Hobart departure. A dispensation was granted for landing no later than 23:40 local time. JQ680 had 170 passengers including 4 children, 2 infants, and 6 crew on-board. The aircraft arrived at 23:38 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 28 August 2023

Aircraft: B737

Registration: VH-VXF

Operator: Qantas

Operation: Arrival

Circumstances Leading to Request: Qantas flight QF749 (Sydney to Adelaide) was delayed arriving at Adelaide Airport due to delays in accessing the flight plan which affected the fuel order. A dispensation was granted for landing no later than 23:10 local time. QF749 had 79 passengers and 6 crew on-board. The aircraft arrived at 23:00 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 30 August 2023

Aircraft: A320

Registration: VH-VGY

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ680 (Hobart to Adelaide) was delayed arriving at Adelaide Airport due to a boarding system outage that affected Jetstar flights across Australia. A dispensation was granted for landing no later than 23:59 local time. JQ680 had 180 passengers and 6 crew on-board. The aircraft arrived at 23:51 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 31 August 2023

Aircraft: B737

Registration: VH-VUW

Operator: Virgin Australia

Operation: Arrival

Circumstances Leading to Request: Virgin Australia flight VA722 (Perth to Adelaide) was delayed arriving at Adelaide Airport due to two evacuations of Perth airport due to smoke in the terminal. A dispensation was granted for landing no later than 23:30 local time. VA722 had 90 passengers including 1 wheelchair, and 6 crew on-board. The aircraft arrived at 23:10 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 07/08/2023 – 03/09/2023

GOLD COAST AIRPORT

DETAILS OF DISPENSATION

Date: 14/08/2023

Aircraft: B737

Registration: VH-IWQ

Operator: Virgin Australia

Operation: Departure

Circumstances Leading to Request: Virgin Australia flight VA756 (Gold Coast to Melbourne) was delayed departing from Gold Coast Airport due to an aircraft change and full re-crew following a security incident at Sydney Airport. A dispensation was granted for take-off no later than 23:15 local time. VA756 had 100 passengers including 1 wheelchair and 4 infant and 6 crew on-board. The aircraft departed at 23:05 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 30 August 2023

Aircraft: A320

Registration: VH-VFY

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ420 (Sydney to Gold Coast) was delayed arriving at Gold Coast Airport due to a boarding system outage that affected Jetstar flights across Australia. A dispensation was granted for landing no later than 23:30 local time. JQ420 had 180 passengers and 6 crew on-board. The aircraft arrived at 23:08 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 31 August 2023

Aircraft: B737

Registration: VH-VUE

Operator: Virgin Australia

Operation: Arrival

Circumstances Leading to Request: Virgin Australia flight VA761 (Melbourne to Gold Coast) was delayed arriving at Gold Coast Airport due to delays in the installation and testing of new headsets. A dispensation was granted for landing no later than 23:20 local time. VA761 had 165 passengers and 6 crew on-board. The aircraft arrived at 23:15 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

ESSENDON FIELDS AIRPORT

There were no approved dispensations for Essendon Fields Airport during this period

REFUSED DISPENSATIONS

INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 07/08/2023 – 03/09/2023

ADELAIDE AIRPORT

There were no refused dispensations for Adelaide Airport during this period.

GOLD COAST AIRPORT

There were no refused dispensations for Gold Coast Airport during this period.

ESSENDON FIELDS AIRPORT

There were no refused dispensations for Essendon Fields Airport during this period.