

**APPROVED DISPENSATIONS****INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 10/08/2021 – 24/08/2021****DETAILS OF DISPENSATION**

Date: Tuesday, 10 August 2021  
Aircraft: A330  
Registration: VH-QPB  
Operator: Qantas Airways  
Operation: Departure

**Circumstances Leading to Request:** Qantas Airways flight QF7324 (Sydney to Melbourne) was delayed departing Sydney Airport due to electrical issues with the aircraft. QF7324 had two crew on board. A dispensation was granted for departure no later than 11:30pm local time. The aircraft departed at 11:21pm local time.

**Approved: Yes**

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

**DETAILS OF DISPENSATION**

Date: Thursday, 12 August 2021  
Aircraft: 757-200  
Registration: SX-APX  
Operator: Airwork  
Operation: Departure

**Circumstances Leading to Request:** Airwork flight AWK2 (Sydney to Auckland) was delayed departing Sydney Airport due to tarmac congestion. AWK2 had two crew on board. A dispensation was granted for departure no later than 11:45pm local time. The aircraft departed at 11:39pm local time.

**Approved: Yes**

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

**DETAILS OF DISPENSATION**

Date: Wednesday, 18 August 2021  
Aircraft: A330  
Registration: VH-EBV  
Operator: Qantas Airways  
Operation: Departure

**Circumstances Leading to Request:** Qantas Airways Flight QF7322 (Sydney to Perth) was delayed departing Sydney Airport due to technical issues. An alternate aircraft was arranged. The flight was carrying critical medical cargo. QF7322 had three crew on board. A dispensation was granted for departure no later than 11:45pm local time. The aircraft departed at 11:45pm local time.

**Approved: Yes**

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Friday, 20 August 2021  
Aircraft: 777-300  
Registration: A7-BEO  
Operator: Qatar Airways  
Operation: Departure

**Circumstances Leading to Request:** Qatar Airways Flight QR909 (Sydney to Doha) was delayed departing Sydney Airport due to unforeseen ground handling issues associated with its departure and safety concerns of a shortened runway due to runway works. QR909 had 157 passengers and 17 crew on board. A dispensation was requested for departure over the city no later than 11:25pm local time. The aircraft departed at 11:22pm local time.

**Approved: Yes**

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Monday, 23 August 2021  
Aircraft: A330  
Registration: VH-EBQ  
Operator: Qantas Airways  
Operation: Departure

**Circumstances Leading to Request:** Qantas Airways Flight QF7325 (Sydney to Melbourne) was delayed departing Sydney Airport due to COVID-19 biosecurity requirements. The flight was carrying critical medical cargo. QF7322 had two crew on board. A dispensation was granted for departure no later than 11:45pm local time. The aircraft departed at 11:37pm local time.

**Approved: Yes**

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

**DISPENSATION REQUESTS REFUSED**

**INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 10/08/2021– 24/08/2021**

**There were no refused applications during this period.**

**APPROVED DISPENSATIONS**

**INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 10/08/2021 – 24/08/2021**

**DETAILS OF DISPENSATION**

Date: Sunday, 22 August 2021  
Aircraft: A320  
Registration: VH-VQL  
Operator: Jetstar Airways  
Operation: Arrivals

**Circumstances Leading to Request:** Jetstar Airways flight JQ782 (Brisbane to Adelaide) was delayed arriving into Adelaide Airport due to engineering issues. An alternate aircraft was arranged. JQ782 had 74 passengers and 6 crew on board. A dispensation was granted for landing no later than 00:30am local time. The aircraft landed at 00:24am local time.

**Approved: Yes**

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

**There were no applications for Gold Coast Airport during this period.**

**There were no applications for Essendon Fields Airport during this period.**