

APPROVED DISPENSATIONS**INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 07/11/2019 – 20/11/2019****DETAILS OF DISPENSATION**

Date: Friday, 8 November 2019
Aircraft: A330
Registration: VH-EBC
Operator: Qantas Airways
Operation: Arrival

Circumstances Leading to Request: Qantas Airways flight QF582 (Perth to Sydney) was delayed departing Perth Airport due to a forward cargo hold fault detected during pushback. A dispensation was approved to land no later than 11:25pm. There were 267 passengers and 10 crew members on board. The aircraft landed at 11:15pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Friday, 8 November 2019
Aircraft: B737-800
Registration: VH-YFP
Operator: Virgin Australia
Operation: Arrival

Circumstances Leading to Request: Virgin Australia flight VA544 (Gold Coast to Sydney) was delayed from departing Gold Coast Airport due to a fail to board passenger which required their luggage to be removed. A dispensation was approved to land no later than 11:20pm. There were 167 passengers and six crew members on board. The aircraft landed at 11:13pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Friday, 8 November 2019
Aircraft: B737-800
Registration: VH-YFQ
Operator: Virgin Australia
Operation: Arrival

Circumstances Leading to Request: Virgin Australia flight VA546 (Gold Coast to Sydney) was delayed from departing Gold Coast Airport due to two disruptive passengers, who required AFP to attend and escort them from the aircraft. A dispensation was approved to land no later than 11:20pm. There were 125 passengers and six crew members on board. The aircraft landed at 11:09pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Friday, 8 November 2019
Aircraft: B737-800
Registration: VH-YUU
Operator: Virgin Australia
Operation: Arrival

Circumstances Leading to Request: Virgin Australia flight VA895 (Melbourne to Sydney) was delayed arriving into Sydney Airport due to extended single runway operations and the prioritisation of two medivac flights at Sydney Airport. A dispensation was approved to land no later than 11:30pm. There were 179 passengers and six crew members on board. The aircraft landed at 11:11pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Saturday, 9 November 2019
Aircraft: A320
Registration: VH-XJE
Operator: Jetstar Airways
Operation: Departure

Circumstances Leading to Request: Jetstar Airways flight JQ611 (Sydney to Avalon) was delayed due to an engineering fault detected after the aircraft had pushed back from the terminal and another aircraft was sourced. A dispensation was approved to depart no later than 11:58pm. There were 177 passengers and 29 crew members on board. The aircraft departed at 11:56pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Sunday, 10 November 2019
Aircraft: A380
Registration: A7-AFP
Operator: Qatar Airways
Operation: Departure

Circumstances Leading to Request: Qatar Airways flight QR909 (Sydney to Doha) was delayed due to a technical issue that was detected after the flight was fully boarded. A dispensation was approved to depart no later than 11:45pm. There were 343 passengers and 29 crew members on board. The aircraft departed at 11:29pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Tuesday, 12 November 2019
Aircraft: B747F
Registration: 9V-SFN
Operator: Singapore Airlines Cargo
Operation: Arrival

Circumstances Leading to Request: Singapore Airlines Cargo flight SQ7298 (Singapore to Sydney) was diverted to Melbourne for safety reasons due to insufficient holding fuel. A dispensation was approved to land at Sydney Airport no later than 11:30pm. The aircraft landed at 11:21pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Friday, 15 November 2019
Aircraft: B747
Registration: VH-OEI
Operator: Qantas Airways
Operation: Departure

Circumstances Leading to Request: Qantas Airways flight QF25 (Sydney to Haneda) had pushed back when an engineering issue occurred. A dispensation was approved to depart no later than 11:40pm. There were 364 Passengers and 17 crew members on board. The aircraft departed at 11:28pm.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DISPENSATION REQUESTS REFUSED

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 07/11/2019 – 20/11/2019

DETAILS OF DISPENSATION

Date: Tuesday, 12 November 2019
Aircraft: B747F
Registration: 9V-SFN
Operator: Singapore Airlines Cargo
Operation: Departure

Circumstances Leading to Request: Singapore Airlines Cargo flight SQ7298 (Sydney to Auckland) was diverted to Melbourne on the previous sector due to Air Traffic Control Holding in Sydney. A dispensation was requested to depart no later than 1am, however this was refused.

Approved: No

Reasons for not granting Dispensation: The Delegate was not satisfied that exceptional circumstances existed.

DETAILS OF DISPENSATION

Date: Wednesday, 13 November 2019
Aircraft: A320
Registration: VH-VFK
Operator: Jetstar Airways
Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ524 (Melbourne to Sydney) was delayed on the previous sector due to an engineering problem. A dispensation was requested to land no later than 11:15pm, however this was refused.

Approved: No

Reasons for not granting Dispensation: The Delegate was not satisfied that exceptional circumstances existed.

DETAILS OF DISPENSATION

Date: Sunday, 17 November 2019
Aircraft: A320
Registration: VH-VNO
Operator: Tigerair Australia
Operation: Arrival

Circumstances Leading to Request: Tigerair Australia flight TT625 (Gold Coast to Sydney) was delayed into the Gold Coast due to thunderstorms. A dispensation was requested, however this was refused. There were 177 passengers and six crew members on board.

Approved: No

Reasons for not granting Dispensation: The Delegate was not satisfied that exceptional circumstances existed.

ADELAIDE AIRPORT: 07/11/2019 – 20/11/2019

Applications Approved

Date	Carrier	Aircraft Type	Movement	Summary of events
08/11/2019	Emirates	B777-200	Departure	Emirates Airline flight EK441 (Adelaide to Dubai) was delayed due to a water leak detected on the flight arriving into Adelaide Airport. A dispensation was approved to depart no later than 11:30pm. There were 233 passengers and 20 crew members on board. The aircraft departed at 11:10pm.

Applications Refused

Date	Carrier	Aircraft Type	Movement	Summary of events
07/11/2019	Jetstar Airways	A320	Arrival	Jetstar Airways flight JQ776 (Melbourne to Adelaide) was delayed into Melbourne on the previous sector. A dispensation was requested, however was refused as there were no exceptional circumstances to justify the granting of a dispensation.

There were no applications for Gold Coast Airport or Essendon Fields Airport during this period.