

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 09/05/2023 – 21/05/2023

SYDNEY AIRPORT

DETAILS OF DISPENSATION

Date: Monday 15 May 2023

Aircraft: A330

Registration: 9M-MUA

Operator: Malaysia Airlines

Operation: Departure

Circumstances Leading to Request: Malaysia Airlines flight MH6204 (Sydney to Kuala Lumpur) was delayed departing Sydney Airport due to engineering issues with the hydraulics. A dispensation was granted for departing no later than 23:59 local time. MH6204 had 800 sheep and goat and 2 crew on-board. The aircraft departed at 23:37 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Thursday 18 May 2023

Aircraft: B767

Registration: VH-EXZ

Operator: Tasman Cargo Airlines

Operation: Departure

Circumstances Leading to Request: Tasman Cargo Airlines flight HJ2 (Sydney to Auckland) was delayed departing at Sydney Airport due to an issue with pilot documentation. A dispensation was granted for departing no later than 23:59 local time. HJ2 had time sensitive medication, including isotopes for cancer treatments and 3 crew on-board. The aircraft departed at 23:57 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

REFUSED DISPENSATIONS

INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 09/05/2023 – 21/05/2023

There were no refused dispensations for Sydney Airport during this period.

APPROVED DISPENSATIONS**INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 09/05/2023 – 21/05/2023****ADELAIDE AIRPORT****DETAILS OF DISPENSATION**

Date: Wednesday 10 May 2023

Aircraft: A320

Registration: VH-YXU

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ680 (Hobart to Adelaide) was delayed arriving at Adelaide Airport due to a last-minute runway change causing a replan for departure and pre-departure brief. This was exacerbated when the Captain's paperwork was taking longer than usual as he had a query regarding the cargo paperwork. This required ground staff to check and confirm that the cargo hold was following all requirements. A dispensation was granted for landing no later than 23:45 local time. JQ680 had 149 passengers including 1 infant, 7 children and 6 crew on-board. The aircraft arrived at 23:44 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Sunday 14 May 2023

Aircraft: E190

Registration: VH-UYU

Operator: Alliance Airlines

Operation: Arrival

Circumstances Leading to Request: Alliance Airlines flight QF1939 (Brisbane to Adelaide) was delayed arriving at Adelaide Airport due to unwell crew member, requiring a crew change. A dispensation was granted for landing no later than 23:45 local time. QF1939 had 88 passengers and 4 crew on-board. The aircraft at 23:34 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 09/05/2023 – 21/05/2023

GOLD COAST AIRPORT

There were no refused dispensations for Gold Coast Airport during this period.

ESSENDON FIELDS AIRPORT

There were no approved dispensations for Essendon Fields Airport during this period

REFUSED DISPENSATIONS

INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 09/05/2023 – 21/05/2023

ADELAIDE AIRPORT

There were no refused dispensations for Adelaide Airport during this period.

GOLD COAST AIRPORT

There were no refused dispensations for Gold Coast Airport during this period.

ESSENDON FIELDS AIRPORT

There were no refused dispensations for Essendon Fields Airport during this period.