APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 22/05/2023 – 29/05/2023

SYDNEY AIRPORT

DETAILS OF DISPENSATION

Date: 28 May 2023

Aircraft: A330

Registration: VH-EBJ

Operator: Qantas

Operation: Arrival

Circumstances Leading to Request: Qantas flight QF196 (Apia to Sydney) was delayed arriving into Sydney after several engineering delays prior to departure from Apia. Further, a fail to board passenger also delayed departure from Apia. A dispensation was granted to land no later than 23:45 local time. QF196 had 233 passengers and 12 crew on board. The aircraft landed at 23:42 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

REFUSED DISPENSATIONS

INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 22/05/2023 – 29/05/2023

There were no refused dispensations for Sydney Airport during this period.

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 22/05/2023 – 29/05/2023

ADELAIDE AIRPORT

DETAILS OF DISPENSATION

Date: 25 May 2023

Aircraft: B737-800

Registration: VH-XZP

Operator: Qantas

Operation: Arrival

Circumstances Leading to Request: Qantas flight QF749 (Sydney to Adelaide) was delayed in the preceding sector (Adelaide to Sydney) due to engineering issues. This pushed the expected arrival time for the QF749 into the curfew period. A dispensation was granted for landing no later than 23:10 local time. QF749 had 87 passengers and 7 crew on board as well as 45L of perishable breast milk. The aircraft landed at 23:08 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: 29 May 2023

Aircraft: A320

Registration: VH-VQH

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ766 (Sydney to Adelaide) was delayed arriving into Adelaide due to single runway operations at Sydney and engineering issues with the aircraft prior to departure. A dispensation was granted for landing no later than 23:30 local time. JQ766 had 174 passengers, including 3 children, and 6 crew on board. The aircraft landed at 23:21 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 22/05/2023 - 29/05/2023

GOLD COAST AIRPORT DETAILS OF DISPENSATION

Date: Tuesday 24 May 2023

Aircraft: A320

Registration: VH-VQC

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar flight JQ450 (Melbourne to Gold Coast) was delayed arriving at the Gold Coast due to a fault discovered with the aircraft prior to take-off. In addition, there were ATC delays. A dispensation was granted for landing no later than 23:20 local time. JQ450 had 175 passengers and 6 crew members on-board. The aircraft landed at 23:10 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

ESSENDON FIELDS AIRPORT

There were no approved dispensations for Essendon Fields Airport during this period

DISPENSATION REPORT – REFUSED DISPENSATIONS OTHER CURFEW AIRPORTS #8/23

REFUSED DISPENSATIONS

INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 22/05/2023 – 29/05/2023

ADELAIDE AIRPORT

There were no refused dispensations for Adelaide Airport during this period.

GOLD COAST AIRPORT

There were no refused dispensations for Gold Coast Airport during this period.

ESSENDON FIELDS AIRPORT

There were no refused dispensations for Essendon Fields Airport during this period.