

**APPROVED DISPENSATIONS****INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 7/11/2022– 21/11/2022****DETAILS OF DISPENSATION**

Date: Friday 11 November 2022

Aircraft: A321

Registration: VH-VWN

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ536 (Melbourne to Sydney) was delayed arriving in Sydney due to a failed to board passenger. In addition, the aircraft had an engineering issue which required an air start. A dispensation was granted for landing no later than 23:15 local time. JQ536 had 226 passengers including 1 wheelchair passenger, 2 infants, 5 children and 7 crew members on-board. The aircraft landed at 23:06 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

**DETAILS OF DISPENSATION**

Date: Tuesday 15 November 2022

Aircraft: A320

Registration: VH-YXQ

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ612 (Avalon to Sydney) was delayed arriving into Sydney due to an unforeseen internal clean of the aircraft. A dispensation was granted for landing no later than 23:30 local time. JQ612 had 164 passengers and 6 crew members on-board. The aircraft landed at 23:20 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## DETAILS OF DISPENSATION

Date: Tuesday 15 November 2022

Aircraft: A330

Registration: VH-EBJ

Operator: Qantas

Operation: Arrival

**Circumstances Leading to Request:** Qantas flight QF648 (Perth to Sydney) was delayed arriving into Sydney due to an unexpected diversion to Canberra from Perth for additional fuel. In addition, there was an engineering fault. A dispensation was granted for landing no later than 23:30 local time. QF648 had 260 passengers including 1 wheel chair passenger, 3 infants and 8 crew members on-board. The aircraft landed at 23:28 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## DETAILS OF DISPENSATION

Date: Sunday 20 November 2022

Aircraft: A320

Registration: VH-VFH

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ987 (Perth to Sydney) was delayed arriving into Sydney due to an engineering issue. A dispensation was granted for landing no later than 23:55 local time. JQ987 had 175 passengers including 1 infant, 6 children and 6 crew members on-board. The aircraft landed at 23:53 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## DETAILS OF DISPENSATION

Date: Sunday 20 November 2022

Aircraft: B737

Registration: VH-YFH

Operator: Virgin Australia

Operation: Arrival

**Circumstances Leading to Request:** Virgin Australia flight VA441 (Adelaide to Sydney) was delayed arriving into Sydney due to boarding delays, owing to poor weather conditions. A dispensation was granted for landing no later than 23:10 local time. VA441 had 167 passengers including 3 blind passengers, 4 wheelchair passengers and 6 crew members on-board. The aircraft landed at 23:09 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Sunday 20 November 2022

Aircraft: A35J

Registration: BLXI

Operator: Cathay Pacific

Operation: Departure

**Circumstances Leading to Request:** Cathay Pacific flight CX138 (Sydney to Hong Kong) was delayed departing Sydney due to a catering truck breaking down, requiring a substitute. A dispensation was granted for departing no later than 23:35 local time. CX138 had 329 passengers and 15 crew members on-board. The aircraft departed at 23:19 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Sunday 20 November 2022

Aircraft: B737

Registration: VH-YIW

Operator: Virgin Australia

Operation: Departure

**Circumstances Leading to Request:** Virgin Australia flight VA892 (Sydney to Melbourne) was delayed departing Sydney due to an engineering issue. A dispensation was granted for departing no later than 23:50 local time. VA892 had 168 passengers and 6 crew members on-board. The aircraft departed at 23:23 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Monday 21 November 2022

Aircraft: B767

Registration: VH-WQU

Operator: Tasman Cargo Airlines

Operation: Departure

**Circumstances Leading to Request:** Tasman Cargo Airlines flight HJ002 (Sydney to Auckland) was delayed departing Sydney due to weather conditions in Sydney. A dispensation was granted for departing no later than 23:45 local time. HJ002 had 2 passengers, urgent medical goods and 2 crew members on-board. The aircraft departed at 23:26 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **REFUSED DISPENSATIONS**

**INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 7/11/2022–21/11/2022**

**There were no refused dispensations for Sydney Airport during this period.**



INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 7/11/2022–21/11/2022

**GOLD COAST AIRPORT**

**DETAILS OF DISPENSATION**

Date: Friday 11 November 2022

Aircraft: A320

Registration: VH-VQW

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ428 (Sydney to Gold Coast) was delayed arriving at the Gold Coast due to a medical emergency on-board. In addition, there were 5 failed to board passengers and a delay in take-off clearance at Sydney Airport. A dispensation was granted for landing no later than 23:30 local time. JQ428 had 145 passengers including 1 infant, 5 children and 6 crew members on-board. The aircraft landed at 23:11 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

**DETAILS OF DISPENSATION**

Date: Monday 21 November 2022

Aircraft: A320

Registration: VH-VGO

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ428 (Sydney to Gold Coast) was delayed arriving at the Gold Coast due to a late runway change in Sydney. A dispensation was granted for landing no later than 23:30 local time. JQ428 had 180 passengers including 5 infants and 6 crew members on board. The aircraft landed at 23:20 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Monday 21 November 2022

Aircraft: A320

Registration: VH-VQW

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ448 (Melbourne to Gold Coast) was delayed arriving at the Gold Coast due to unexpected wind changes on route. A dispensation was granted for landing no later than 23:15 local time. JQ448 had 147 passengers including 4 infants, 13 children and 6 crew members on-board. The aircraft landed at 23:03 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **ADELAIDE AIRPORT**

## **DETAILS OF DISPENSATION**

Date: Monday 7 November 2022

Aircraft: A320

Registration: VH-VGP

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ975 (Perth to Adelaide) was delayed arriving into Adelaide due to an issue with paperwork relating to the carriage of an electric wheelchair. This resulted in the wheelchair being moved to a different location in the cargo hold, delaying departure out of Perth. A dispensation was granted for landing no later than 23:20 local time. JQ975 had 172 passengers including 2 wheelchair passengers, 7 infants, 7 children and 6 crew members on-board. The aircraft landed at 23:15 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Thursday 10 November 2022

Aircraft: E190

Registration: VH-UYF

Operator: Qantas

Operation: Arrival

**Circumstances Leading to Request:** Qantas flight QF1939 (Brisbane to Adelaide) was delayed due to a late arrival into Brisbane followed by a bag count discrepancy that required another bag count. These factors delayed departure out of Brisbane. A dispensation was granted for landing no later than 23:35 local time. QF1939 had 75 passengers and 6 crew on board. The aircraft landed at 23:28 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Friday 11 November 2022

Aircraft: B737

Registration: VH-YIU

Operator: Virgin Australia

Operation: Arrival

**Circumstances Leading to Request:** Virgin Australia flight VA583 (Canberra to Adelaide) was delayed arriving into Adelaide due to a delay in the previous sector (Adelaide to Canberra) owing to an APU fail that required an air start. The problem was not able to be rectified prior to departure, therefore the same was required for flight VA583. A dispensation was granted for landing no later than 23:10 local time. VA583 had 153 passengers including 63 children and 6 crew members on-board. The aircraft landed at 23:06 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## DETAILS OF DISPENSATION

Date: Saturday 12 November 2022

Aircraft: A320

Registration: VH-VFH

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ975 (Perth to Adelaide) was delayed arriving into Adelaide due to a delay in the previous sector (Adelaide to Perth) owing to thunderstorm activity. In addition, the tarmac was closed for several hours due to a lightning risk, creating extensive delays. Further, Jetstar were required to offload the baggage of 2 failed to board passengers. A dispensation was granted for landing no later than 23:59 local time. JQ975 had 186 passengers including 2 infants, 3 wheelchair passengers, 10 children and 6 crew members on-board. The aircraft landed at 23:46 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## DETAILS OF DISPENSATION

Date: Saturday 12 November 2022

Aircraft: A320

Registration: VH-VFP

Operator: Jetstar Airways

Operation: Arrival

**Circumstances Leading to Request:** Jetstar Airways flight JQ800 (Brisbane to Adelaide) was delayed arriving into Adelaide due to a delay in the previous sector (Adelaide to Brisbane) owing to thunderstorm activity. In addition, the tarmac was closed for several hours due to a lightning risk, creating a further delay. A dispensation was granted for landing no later than 23:40 local time. JQ800 had 143 passengers including 1 wheelchair passenger, 3 infants, 17 children and 6 crew members on-board. The aircraft landed at 23:35 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.



## **DETAILS OF DISPENSATION**

Date: Sunday 13 November 2022

Aircraft: B737

Registration: VH-VZC

Operator: Qantas

Operation: Arrival

**Circumstances Leading to Request:** Qantas flight QF747 (Sydney to Adelaide) was delayed arriving into Adelaide due to a delay in the previous sector (Adelaide to Sydney) owing to 2 failed to board passengers. In addition, the aircraft had an engineering issue that required rectification prior to departure out of Sydney. A dispensation was granted for landing no later than 23:59 local time. QF747 had 174 passengers and 6 crew members on-board. The aircraft landed at 23:55 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Sunday 13 November 2022

Aircraft: A320

Registration: VH-VFH

Operator: Jetstar

Operation: Arrival

**Circumstances Leading to Request:** Jetstar flight JQ800 (Brisbane to Adelaide) was delayed arriving into Adelaide due to the aircraft being blocked by another aircraft in Brisbane. A dispensation was granted for landing no later than 23:30 local time. JQ800 had 179 passengers including 14 children and 6 crew members on-board. The aircraft landed at 23:25 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## DETAILS OF DISPENSATION

Date: Sunday 13 November 2022

Aircraft: B737

Registration: VH-YFR

Operator: Virgin Australia

Operation: Arrival

**Circumstances Leading to Request:** Virgin Australia flight VA583 (Canberra to Adelaide) was delayed arriving into Adelaide due to a delay in the previous sector (Adelaide to Canberra) owing to a delay in boarding passengers. In addition, there were boarding delays on flight VA583 as a result of poor weather in Canberra. A dispensation was granted for landing no later than 23:15 local time. VA583 had 125 passengers including 1 infant, 1 wheelchair passenger and 6 crew members on-board. The aircraft landed at 23:00 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## DETAILS OF DISPENSATION

Date: Monday 14 November 2022

Aircraft: B737

Registration: VH-VXH

Operator: Qantas

Operation: Arrival

**Circumstances Leading to Request:** Qantas flight QF747 (Sydney to Adelaide) was delayed arriving into Adelaide due to a delay out of Sydney, owing to network disruptions. In addition, QF747 had urgent medical supplies on-board. A dispensation was granted for landing no later than 23:20 local time. QF747 had 141 passengers including 2 wheelchair passengers and 6 crew members. The aircraft landed at 23:05 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Saturday 19 November 2022

Aircraft: B737

Registration: VH-VZA

Operator: Qantas

Operation: Arrival

**Circumstances Leading to Request:** Qantas flight QF747 (Sydney to Adelaide) was delayed arriving into Adelaide due to a delay in the previous sector (Adelaide to Sydney) owing to a mechanical fault. A dispensation was granted for landing no later than 23:20 local time. QF747 had 148 passengers and 6 crew members on-board. The aircraft landed at 23:15 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Sunday 20 November 2022

Aircraft: E190

Registration: VH-UYF

Operator: Qantas

Operation: Arrival

**Circumstances Leading to Request:** Qantas flight QF1939 (Brisbane to Adelaide) was delayed arriving into Adelaide due to stronger than expected thunderstorms in Brisbane that delayed departure. A dispensation was granted for landing no later than 23:15 local time. QF1939 had 70 passengers including 1 wheelchair passenger and 4 crew members on-board. The aircraft landed at 23:07 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **DETAILS OF DISPENSATION**

Date: Sunday 20 November 2022

Aircraft: B737

Registration: VH-VZY

Operator: Qantas

Operation: Arrival

**Circumstances Leading to Request:** Qantas flight QF747 (Sydney to Adelaide) was delayed arriving into Adelaide due to a delay in the previous sector (Adelaide to Sydney) owing to unexpected winds in Sydney. A dispensation was granted for landing no later than 23:30 local time. QF747 had 139 passengers and 6 crew members on-board. The aircraft landed at 23:16 local time.

**Approved:** Yes

**Reasons for Approval:** The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

## **ESSENDON FIELDS AIRPORT**

**There were no approved dispensations for Essendon Fields Airport during this period.**



**REFUSED DISPENSATIONS**

**INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 7/11/2022 – 21/11/2022**

**ADELAIDE AIRPORT**

**There were no refused dispensations for Adelaide Airport during this period.**

**GOLD COAST AIRPORT**

**There were no refused dispensations for Gold Coast Airport during this period.**

**ESSENDON FIELDS AIRPORT**

**There were no refused dispensations for Essendon Fields Airport during this period.**

