

APPROVED DISPENSATIONS**INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 15/06/2021 – 23/06/2021****DETAILS OF DISPENSATION**

Date: Wednesday, 16 June 2021
Aircraft: B738
Registration: VH-VZX
Operator: Qantas Airways
Operation: Arrival

Circumstances Leading to Request: Qantas Airways flight QF6158 (Darwin to Sydney) was delayed departing Darwin Airport due to COVID-19 biosecurity protocols. A dispensation was granted for landing no later than 11:59pm local time. The aircraft landed at 11:28pm local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Sunday, 20 June 2021
Aircraft: B777-300
Registration: A7-BEW
Operator: Qatar Airways
Operation: Departure

Circumstances Leading to Request: Qatar Airways flight QR909 (Sydney to Doha) was delayed departing Sydney Airport due to a mechanical issue. A dispensation was granted for take-off no later than 11:45pm local time. The aircraft departed at 11:13pm local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 15/06/2021 – 23/06/2021

There were four applications for Adelaide Airport during this period.

DETAILS OF DISPENSATION

Date: Friday, 18 June 2021
Aircraft: E190
Registration: VH-UYO
Operator: Qantas Airlines
Operation: Arrival

Circumstances Leading to Request: Qantas Airlines flight QF1953 (Darwin to Adelaide) was delayed arriving into Adelaide Airport due to engineering issues. A dispensation was granted for landing no later than 11:59pm local time. QF1953 had 51 passengers and 4 crew on board. The aircraft landed at 11:10pm local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Friday, 18 June 2021
Aircraft: B737-800
Registration: VH-VON
Operator: Jetstar Airlines
Operation: Arrival

Circumstances Leading to Request: Virgin Australia flight VA581 (Canberra to Adelaide) was delayed arriving into Adelaide Airport due to engineering issues. A dispensation was granted for landing no later than 11:40pm local time. VA581 had 143 passengers and 6 crew on board. The aircraft landed at 11:20pm local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Saturday, 19 June 2021
Aircraft: A320
Registration: VH-VQR
Operator: Jetstar Airlines
Operation: Arrival

Circumstances Leading to Request: Jetstar Airlines flight JQ805 (Sunshine Coast to Adelaide) was delayed arriving into Adelaide Airport due to engineering issues. A dispensation was granted for landing no later than 11:45pm local time. JQ805 had 146 passengers and 5 crew on board. The aircraft landed at 11:27pm local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

DETAILS OF DISPENSATION

Date: Tuesday, 22 June 2021
Aircraft: RJ100
Registration: VH-NJE
Operator: Cobham Aviation Services
Operation: Arrival

Circumstances Leading to Request: Cobham Aviation Services flight JTE223 (Port Augusta to Adelaide) suffered damage to the fuselage rendering it unserviceable. An alternate aircraft was sourced. A dispensation was granted for landing no later than 11.30pm local time. JTE223 had 77 passengers and 4 crew on board. The aircraft landed at 11.28pm local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

There were no applications for Gold Coast Airport during this period.

There were no applications for Essendon Fields Airport during this period.